Maurice Roy

From:

Scott Syme <ssyme@ssel.ca>

Sent:

Tuesday, August 10, 2021 2:09 PM

To:

Bonnie Fisher; Matt McAllister

Cc:

Adam Bux; Maurice Roy

Subject:

RE: 4540 72 Avenue NE, Canoe

APPENDIX A

Hi Bonnie,

We were not called for field reviews. This also doesn't even meet frost requirements. Furthermore, your photos show that the concrete was mixed on site which is unacceptable unless third party testing was carried out. I chatted with Earle a few months back about reconfiguring the retaining wall footing to be more L-shaped. The conversation was left at Earle would be providing more accurate elevations so we could update a detail. It seems that things proceeded without our guidance or recommendations being followed. I can't sign off on this wall.

Thanks,

Scott Syme, P.Eng

This email and any files transmitted with it are confidential and intended solely for the recipient(s). If you are not the named recipient, you should not disseminate, distribute or copy this email. Please notify the sender immediately by email if you have received this email by mistake and delete this email from your system.

From: Bonnie Fisher

bfwonderwoman49@gmail.com>


Sent: August 10, 2021 12:18 PM

To: Matt McAllister <mmcallister@ssel.ca>; Scott Syme <ssyme@ssel.ca>

Cc: Adam Bux <abux@salmonarm.ca> Subject: 4540 72 Avenue NE, Canoe

Hi Matt and Scott,

Here are the pictures of the retaining wall. The low part will be completed when driveway goes in. The high part is completed.



APPENDIX B

CITY OF SALMON ARM **BUILDING INSPECTION DEPARTMENT**

DATE/TIME <u>August 11, 2021</u> PERMIT# <u>16596B</u>

ADDRESS 4540 – 72 Avenue NE

LEGAL DESCRIPTION Lot 6 Plan KAP84599 6-21-9

YOU ARE HEREBY ORDERED TO

5T()P

ON THIS PROJECT UNTIL THE FOLLOWING INFRACTION(S) IS (ARE) CORRECTED:

The retaining wall at the east side of the house is certified by a registered professional engineer.

> BUILDING INSPECTION DEPARTMENT City OF SALMON ARM **500 - 2 AVENUE NE BOX 40 SALMON ARM, B.C. V1E 4N2**

TELEPHONE: (250) 803-4003

BUILDING INSPECTOR

IT IS AN OFFENCE TO REMOVE THIS PLACARD

SALMONARM

8 - Framing

9 - Insul/VB/AB

10 - Occupancy/Final

INSPECTION RECORD

PHONE: 250.803.4003 | FAX: 250.803.4041

					THORE.	250.00	0.1000	1777.	250.00	70.1013
Permit #:		Address:					уу)	/y	mm	dd
16596		4540 -	-,72 1	Ave	NE		2 0	23		1214
Project Desc.: Standard Bldg. Standard Bldg. with R.P. Review Nature of Inspe								f Insped	ction:	
☐ Complex Bldg. ☐ Other							To	lower		
									V	
The City of Sali by a Registered			(C)							
The CSA has n responsibility t under the supe	o obtain th	e necessary i	nspectio	ons to d	determine Bu	ilding Cod	de compliar			
In the case of Professionals the BC Building	nat the des									
ITEM				DESCRIPT	TION	,	*		COMPLETE	INSP
(1)- As	Par	4		, "	STOP L	JORK"	Ordar	7)+	(
	1 1	(auxice	·	01	2101 6		1 (1		+
	tugust	11, 202	$\frac{1}{2}$		2 4	المحدد -	placed	Due		+
 	the fac	t left	(Est		Retamna	ubll	Has 1	VOT	See	
A-	Dwed	Bry S	wich	val -	P.Erg.					
,,,	V	7			• - 1		· ·			
07	11	7-4	MJ	7		. / ``	10.10	' -	-1	1
(2) Du	Lang S Elon	ied Oct	1/ust 21.	20	<u>lenen</u> ZZ.	ea 1	15/17	45	47	
		2				, ,	2			,
(3) 30	7		- 1/		7	A U.	(7	- W	1.16-	_
19 30	Dus in	ess Vai	15 H	aletal	Deen 1	the the	red t	y The	AHJ	1 1
100	the contract	10+0	tord	NOVE	1011 11	The	000	. > 0.		+
VP	JIMS. (1)	CX K	BUZYL	7 0	All Under	100	Syllic	151h.	a	-
	(2)	Stretura	L rie	جر	SIGN OF	FWW	· AUXY	my le	7	
		(East)	Reta	land	e Wall.			, 1	1	
Note: Whi	the sir	- given	to	Lynn	Morgan	- Mox	for m l	av.	1	
				,						
Nature of Inspec	ction Types				DE INICI	DECTION	DEGLUDE		YES N	10
1 - Footings							REQUIREI			4
2 - Foundation 3 - Backfill					ZNDRE	INSPECT	ION REQU	IKED.	⊔ г	_
4 - Services						5/	\ll			
5 - Potable Water										
6 - DWV Roughin BUILDING INSPECTOR								ECTOP		
7 - Soil Gas Control										

to the freedom of information and protection of privacy act inquires

Information provided by this form may be subject